
No noted repair quantities.

WEST ABUTMENT ELEVATION



EAST ABUTMENT ELEVATION

BILL OF MATERIAL

ITEM	UNIT	QUANTITY
Structural Repair of Concrete (Depth Equal to or Less than 5")	Sq. Ft.	63

LEGEND

Structural Repair of Concrete (Depth Equal to or Less than 5")

Notes:
Quantity for Structural Repair of Concrete has been increased to include additional repair areas not apparent at the time of the inspection. The actual repair areas will be determined by the Resident Engineer. The Contractor will be paid for the quantity furnished.

No repair quantities noted at piers or wingwalls.

SUBSTRUCTURE REPAIR

IL RTE. 137 (BUCKLEY ROAD)
OVER DES PLAINES RIVER
FAP 352 (IL 137), SECTION 56 B-I-2
LAKE COUNTY
STATION 64+63.88
S.N. 049-0063

DATE: 01-14-09

GRAEF, ANHALT, SCHLOEMER & ASSOCIATES INC CHICAGO ILLINOIS

S.D.H.

J.A.Z.

M.S.M.

S.D.H.

DESIGNED

CHECKED

CHECKED

DRAWN